...nts to roads drains and other development works at Shivamandhira road mathru layout

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 1133

Date : 05/05/23

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka Satellite town Sub Division BBMP Blore-64

2. Well Location : Balaji layout 8th Cross

3. Total Well Depth / Drilled in Ft. : 1154

4. Casing Erected in Ft. : 160

5. Water Struck at the Depth of : 1151

6. Total Yield (Measuring method "V" Norch : 6" / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear

8. At the Depth of : 1151

9. Recommended to use Jet Pump / Air Compressor / Submersible ✓ /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

...nts to roads drains and other development works at Shivamandhira road mathru layout

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 1135

Date : 05/05/23

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka Satellite Town Sub-Division BBMP Blore-64

2. Well Location : BHEL Layout 12th Cross

3. Total Well Depth / Drilled in Ft. : 1158

4. Casing Erected in Ft. : 59

5. Water Struck at the Depth of : 1158

6. Total Yield (Measuring method "V" Norch : 6 11 / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear

8. At the Depth of : 1158

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

...ments to roads drains and other development works at Shivamandhira road mathru layout

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 1136

Date : 05/09/23

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka Satellite Town Sub-Division BBMP Bloro-64

2. Well Location : G. Ramaiah Enclave 3rd Cross

3. Total Well Depth / Drilled in Ft. : 1181

4. Casing Erected in Ft. : 101

5. Water Struck at the Depth of : 1181

6. Total Yield (Measuring method "V" Norch : 6" / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear

8. At the Depth of : 1181

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

...nts to roads drains and other development works at Shivamandhira road mathru layout

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

BOREWELL COMPLETION REPORT

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Mobile : +91 9342202932 / 9343202932

No. 1134

Date : 05/05/23

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka Satellite Town Sub-Division BBMP Blore-64

2. Well Location : Syndik vihar Layout 7th Main Road

3. Total Well Depth / Drilled in Ft. : 977

4. Casing Erected in Ft. : 82

5. Water Struck at the Depth of : 977

6. Total Yield (Measuring method "V" Norch : 6" / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear

8. At the Depth of : 977

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor